

Freedom of Information Request: Our Reference CTHB_206_19

You asked:

Please can I request a copy of the asbestos records held by the Authority for St Tydfil's Hospital, Merthyr Tydfil in accordance with the requirements of the Duty to manage asbestos in non-domestic premises under Section 4 of The Control of Asbestos Regulations 2006 and Section 4 of The Control of Asbestos Regulations 2012.

Our response:

Please see requested information attached. Please note, Cwm Taf University Health Board sold St Tydfil's Hospital on 6 December 2013.

Showing records for	All Asbestos Types and All Product Types
Showing material records for	1 Site

Important note	Disclaimer
Please note that this document is intended as a guideline only and is to be used in conjunction with the full report and specific material assessment information	Where survey information has been recently added, such information should be regarded as interim, pending the issue of the final report. Final reports are available in the 'attachments' section of the site view.

Material Assessments

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0001	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Stairs TS221	Beige tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0002	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Stairs Ts221	Brown edging strips 50.0m Run	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0003	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Cupboard 1	Beige tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0004	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Meeting room TS207	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0005	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Male wc TS203	Black skirting 50.0m Run	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0006	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Male wc TS203	Grey linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0007	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Consulting TS201	Beige tile and bitumen 25.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0008	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Records/reception TS208	Beige tile and bitumen 25.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0009	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Store TS204	White tile and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0010	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Store TS202	White tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0011	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Female wc TS205	Black skirting 50.0m Run	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0012	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Female wc TS205	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0013	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Admissions TS206	Beige tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0014	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Senior nurse TS209	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0015	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Corridor TS218	White tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0016	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Lobby TS211	White tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0017	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Medical records TS217	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0018	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Medical records TS217	Black skirting 50.0m Run	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0019	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Consulting TS216	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0020	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Secretaries TS215	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0021	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Consulting TS210	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0022	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Consulting TS214	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0023	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Store TS213	Beige tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0024	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Consulting TS212	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0025	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Stairs TS220	Brown vinyl 50.0m Run	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0026	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Stairs TS220	Beige tile 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0027	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Stairs TS220	Brown vinyl 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0028	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Stairs TS220	Boxing to pipe work 50.0m ²	Sampled	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0029	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Store TS220a	Beige tile 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0030	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Lobby TS219	Bitumen membrane Small Amounts	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0031	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Office TS236	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0032	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Seclusion room TS242	Black skirting 50.0m Run	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0033	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Assisted bathroom TS244	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0034	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Store TS243	No Asbestos N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0035	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Male wc TS241	Black skirting 25.0m Run	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0036	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Female wc TS240	Black skirting 25.0m Run	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0037	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Disabled wc TS239	Black skirting 25.0m Run	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0038	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Shower TS238	Black skirting 25.0m Run	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0039	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	5 Bed ward TS245	Beige tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0040	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Nurse sub-station TS246	Beige tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0041	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Corridor TS250	Beige tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0042	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Corridor TS250	Light cream tile and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0043	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Corridor TS250	Cream tile and bitumen Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0044	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	5 Bed ward TS247	Beige tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0045	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Smoking room TS248	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0046	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Day/dining room TS248a	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0047	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Smoking room TS248b	Beige linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0048	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Ward pantry TS249	Bitumen paste Small Amounts	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0049	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Office TS237	Insulating panel 10.0m ²	Sampled	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0050	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Corridor TS253 Ceiling void	Flange gasket Small Amounts	Sampled	Gasket	No Visible	Encapsulated Textile/Paper	Chrysotile	Low	5	5	10
1077922/0051	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Clean utility TS233 Underside of sink	Acoustic pads 2 Items	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0052	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Clean utility TS233	Brown tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0053	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Corridor TS253	Beige tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0054	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Corridor TS251	Cream tile and bitumen Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0055	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Lift TS251a	Cream tile and bitumen Small Amounts	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0056	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Lift TS251a	Light brown tile 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0057	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Stairs TS252	Insulating panel 10.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0058	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Dirty utility TS232	White panels 50.0m ²	Sampled	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0059	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Dirty utility TS232 Underside of sink	Acoustic pads 2 Items	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0060	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Dirty utility TS232	Black skirting 25.0m Run	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0061	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Lift TS251a Electric Cupboard	Electric box N/A	Presumed Asbestos	Rope	No Visible	N/A	Asbestos	Low	5	0	5
1077922/0062	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Wc TS235	Beige tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0063	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Staff base TS234	White panels 50.0m ²	Visually Similar To	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0064	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Staff base TS234	Beige tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0065	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Day Room TS222	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0066	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Office TS223	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0067	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Single bed ward TS224	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0068	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Single bed ward TS225	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0069	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Single bed ward TS226	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0070	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Store TS255	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0071	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Staff wc TS254a	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0072	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Wc TS228	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0073	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Bathroom TS227	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0074	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Corridor TS254	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0075	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Secure room TS229	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0076	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	5 bed war TS231	Beige tile and bitumen 50.0m Run	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0077	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Wc TS230a	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0078	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 1	Bathroom TS230	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0079	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Utility TS262	Acoustic pad Small Amounts	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0080	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Store TS290a	Fawn coloured tile and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0081	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Stairs/lobby TS290	Black nosing 10.0m Run	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0082	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Store TS290a	Brown nosing Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0083	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Wc TS283	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0084	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Corridor TS289	White panels 50.0m ²	Sampled	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0085	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Corridor TS289	Beige tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0086	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Single bed ward TS264	Beige tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0087	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Single bed ward TS264	White panels 50.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0088	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Single bed ward TS265	White panels 50.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0089	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Single bed TS265	Beige tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0090	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	5 bed ward TS266	White panels 50.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0091	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	5 bed ward TS266	Beige tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0092	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Single bed ward TS261	White panels 50.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0093	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Single bed TS261	Beige tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0094	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Stairs/lobby TS290	White panels 50.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0095	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Single bed ward TS260	White panels 50.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0096	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Single bed ward TS260	Beige tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0097	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Male wc TS259	White panels 10.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0098	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Female wc TS258	White panels 50.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0099	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	5 bed ward TS257	White panels 50.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0100	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	5 bed ward TS257	Beige tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0101	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	5 bed ward TS257	Cream tie and bitumen Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0102	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Dirty utility TS267	White panel 50.0m ²	Sampled	Insulating Board	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0103	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Dirty utility TS267 Underside of sink	Acoustic pad 1 Item	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0104	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Wc TS270	Beige tile and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0105	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Wc TS270	White panel 5.00m ²	Visually Similar To	Insulating Board	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0106	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Staff base TS269	Cream tile and bitumen 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0107	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Staff base TS269	White panel 5.00m ²	Visually Similar To	Insulating Board	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0108	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Office TS271	Bitumen paper insulator 50.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0109	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Corridor TS286	Cream tie and bitumen Small Amounts	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0110	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Switch TS272a	Beige tile and bitumen 2.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0111	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 3	Lift motor room	No Access N/A	No Access - Presumed Asbestos	Select Product	No Visible	N/A	No Access	Very Low	3	0	3
1077922/0112	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 3	Lift motor room Electric box	Electrics N/A	Presumed Asbestos	Rope	No Visible	N/A	Asbestos	Low	5	0	5

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0113	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Office TS272	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0114	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Clean utility TS268 Underside of sink	Acoustic pad 1 Item	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	0	3
1077922/0115	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Clean utility TS268	Brown floor tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0116	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Lift TS288	Fawn coloured tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0117	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Lift TS288	Cream tie and bitumen Small Amounts	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0118	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Stairs TS282	White panel 50.0m ²	Visually Similar To	Insulating Board	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0119	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Store TS278	No Asbestos N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0120	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Assisted bathroom TS279	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0121	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Bathroom TS277	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0122	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Male wc TS276	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0123	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Disabled wc TS274	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0124	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Waste TS273	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0125	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Female wc TS275	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0126	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Corridor TS285	Beige tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0127	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Corridor TS285	Cream tile and bitumen Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0128	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Nurse sub-station TS281	Beige tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0129	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	5 bed ward TS252	Beige tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0130	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	5 bed ward TS280	Beige tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0131	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Smoking room TS283	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0132	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Smoking room TS283a	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0133	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Smoking room TS283b	Beige linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0134	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Ward pantry TS287 Underside of sink	Acoustic pads 4 Items	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0135	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 2	Ward pantry TS287	Acoustic pad 1 Item	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0136	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Lift shaft	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0137	Condition Monitoring Survey	Ext	St Tydfils, Psychiatric Unit/G	Front entrance	Tongue and groove boarding 50.0m ²	Sampled	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0138	Condition Monitoring Survey	Ext	St Tydfils, Psychiatric Unit/G	Front of building Wall	Bitumen membrane 50.0m Run	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	Chrysotile	Very Low	2	1	3

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0139	Condition Monitoring Survey	Ext	St Tydfils, Psychiatric Unit/F 1	Adjacent 5 bed ward TS231	Bitumen lining to concrete slabs 50.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0140	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Consulting room TF009	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0141	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Psychology office TF010	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0142	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Corridor 2 TF005	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0143	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Consulting room TF008a	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0144	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Consulting room TF008	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0145	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Library TF007	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0146	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Consulting room TF006	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0147	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Female wc TF002	Grey linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0148	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Kitchen TF004	Acoustic pad 1 Item	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0149	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Male wc TF003	Black cistern Small Amounts	Sampled	Plastics	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0150	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Lobby	Beige tile and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0151	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Corridor 1 TF001	Grey linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0152	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Male wc TF003	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0153	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Kitchen TF004	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0154	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Lobby TS016	Grey linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0155	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Store TF018	Grey linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0156	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Corridor TF014	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0157	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Consulting room TF017	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0158	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Consulting room TF015	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0159	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Lobby TF011	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0160	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Cupboard TF012	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0161	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Office TF115	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0162	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Office TF116	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0163	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Kitchen TF117	Speckled linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0164	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Kitchen TF117	Acoustic pad 1 Item	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0165	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Corridor TF132	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0166	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Creditors TF113	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0167	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Office TF114	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0168	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Store TF112	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0169	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Office TF119	Boxing to beam 10.0m ²	Sampled	Insulating Board	No Visible	Painted/Encapsulated Board	Asbestos Removed	Non asbestos	0	0	0
1077922/0170	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Office TF119a Ceiling	Boxing to beam 10.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	Amosite	Low	5	3	8

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0171	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Office TF118	Boxing to beam, and soffit board 10.0m ²	Sampled	Insulating Board	No Visible	Painted/Encapsulated Board	Asbestos Removed	Non asbestos	0	0	0
1077922/0172	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Male wc TF123	Beige linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0173	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Kitchen TF125	Acoustic pads Small Amounts	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0174	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Kitchen TF125	Off white linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0175	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Photocopier room TF121	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0176	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Corridor TF130	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0177	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Computers TF124	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0178	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Corridor TF129	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0179	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Attic	Bitumen membrane, covers front underside of roof only 50.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0180	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Office TF122	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0181	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Supplies TF126	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0182	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Office TF127	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0183	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Office TF128	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0184	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Stairwell TF101	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0185	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Female Wc TF102	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0186	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Office TF103	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0187	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Male wc TF104	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0188	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Secretaries office TF105	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0189	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Store TF106	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0190	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Office TF107	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0191	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Finance Office TF108	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0192	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Corridor TF133	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0193	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Finance Office TF110	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0194	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Director of finance TF111	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0195	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Server TF109	Beige linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0196	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Stairwell TF201	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0197	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Corridor TF206	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0198	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Store TF202	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0199	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Store TF203	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0200	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Store TF204	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0201	Condition Monitoring Survey	Int	St Tydfils, Central Offices/F 1	Store TF205	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0202	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Secretary TF022	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0203	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Office TF026 Floor	Red linoleum 50.0m ²	Sampled	Vinyl	No Visible	N/A	N/A	Non asbestos	0	0	0
1077922/0204	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Kitchen TF023	Acoustic pad 1 Item	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0205	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Kitchen TF023	Beige linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0206	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Crossroads office TF021	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0207	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Lobby TF020	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0208	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Corridor TF027	Cream tile and bitumen 10.0m ²	Sampled	Vinyl	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0209	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Corridor TF027 Floor	Green tile and bitumen 1.00m ²	Sampled	Vinyl	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0210	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Office TF029	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0211	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Waiting TF028	Beige linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0212	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Lobby TF030	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0213	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Corridor TF027	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0214	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Stairwell TF019	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0215	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Kitchen TF035	Acoustic pad Small Amounts	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0216	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Kitchen TF034	Beige linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0217	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Corridor TF031	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0218	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Office TF033	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0219	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Office TF032a	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0220	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Office TF032	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0221	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Wc TF035	Black cistern Small Amounts	Sampled	Plastics	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0222	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Wc TF035	Beige linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0223	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Corridor TF037	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0224	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Office TF037a	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0225	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Boiler/store TF024	Grey floor tile and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0226	Condition Monitoring Survey	Int	St Tydfils, Central Offices/B	Boiler Room Electric boxes	Boiler Room Wall N/A	Presumed Asbestos	Rope	No Visible	N/A	Asbestos	Low	5	0	5
1077922/0227	Condition Monitoring Survey	Int	St Tydfils, Central Offices/B	Boiler Room Electric boxes	Fuse flash guards presumed to be inside electrics Small Amounts	Presumed Asbestos	Cloth	No Visible	N/A	Asbestos	Low	5	0	5
1077922/0229	Condition Monitoring Survey	Int	St Tydfils, Central Offices/B	Boiler Room	Debris Small Amounts	Sampled	Debris	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/0230	Condition Monitoring Survey	Int	St Tydfils, Central Offices/B	Boiler Room	White pipe lagging Small Amounts	Presumed Asbestos	Thermal Lagging	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/0231	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Office TF036	Insulating board 50.0m ²	Sampled	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0232	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Office TF038	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0233	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Plant room TF025	Cement flue pipe 50.0m Run	Sampled	Cement	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/0234	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Plant room TF025	Rope seal 10.0m Run	Sampled	Rope	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/0235	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Plant room TF025	Flange gasket Small Amounts	Sampled	Gasket	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/0236	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Plant room TF025	White lining Small Amounts	Sampled	Millboard	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/0237	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Plant room TF025	Black flange gasket Small Amounts	Sampled	Gasket	No Visible	Encapsulated Textile/Paper	No Asbestos Detected	Non asbestos	0	0	0
1077922/0238	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Plant room TF025	Debris from previous flange gasket Small Amounts	Sampled	Gasket	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/0239	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Plant room TF025	Jointing sealant in tin Small Amounts	Sampled	Mastic	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0240	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Plant room TF025	Bitumen membrane 10.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0241	Condition Monitoring Survey	Int	St Tydfils, Central Offices/G	Plant room TF025	Bitumen pipe wrap Small Amounts	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0242	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Office 326	White flecked tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0243	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Store 325	Grey linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0244	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Female changing 318	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0245	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Female lockers 317	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0246	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Female toilets/shower	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0247	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Washing area 301	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0248	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Wc 302	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0249	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Wc 303	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0250	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Corridor 1 327	White flecked tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0251	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Corridor 1 327	Debris in screw holes Small Amounts	Sampled	Debris	Visible Debris	Debris	No Asbestos Detected	Non asbestos	0	0	0
1077922/0252	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Linen store 305	Tan coloured linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0253	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Domestic 304	Tan coloured linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0254	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Corridor 2 328	White flecked tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0255	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Female changing 306	Tan coloured linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0256	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Staff rest 307	Tan coloured linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0257	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Store 308	Tan coloured linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0258	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	CLNR store 311	White flecked tile and bitumen Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0259	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Cleaner 309	White flecked tile and bitumen 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0260	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Linen store 310	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0261	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Male toilet/showers 312	Grey linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0262	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Male changing 316	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0263	Condition Monitoring Survey	Int	St Tydfils, Staff Change Linen/G	Corridor 3 329	White flecked tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0264	Condition Monitoring Survey	Ext	St Tydfils, Staff Change Linen/G	Windows	Putty 50.0m Run	Sampled	Mastic	High	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0265	Condition Monitoring Survey	Ext	St Tydfils, Staff Change Linen/G	External of female toilets	Mastic Small Amounts	Sampled	Mastic	Low	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0266	Condition Monitoring Survey	Ext	St Tydfils, Staff Change Linen/G	Walls to front entrance	Textured coating 50.0m ²	Sampled	Textured Coating	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0267	Condition Monitoring Survey	Ext	St Tydfils, Staff Change Linen/G	External of linen store	Mastic bead 50.0m ²	Sampled	Mastic	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0268	Condition Monitoring Survey	Ext	St Tydfils, Staff Change Linen/G	Adjacent male toilet	Bitumen membrane 50.0m Run	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0269	Condition Monitoring Survey	Ext	St Tydfils, Staff Change Linen/G	Roof	Bitumen membrane 50.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0270	Condition Monitoring Survey	Int	Laundry Boiler Room/G	Old Laundry Boiler Room	Fuse flash guards Small Amounts	Sampled	Cloth	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/0271	Condition Monitoring Survey	Int	Laundry Boiler Room/G	Old Laundry Boiler Room	Board for insulating Small Amounts	Sampled	Insulating Board	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0272	Condition Monitoring Survey	Int	Laundry Boiler Room/G	Old Laundry Boiler Room	Melamine board Small Amounts	Sampled	Plastics	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0273	Condition Monitoring Survey	Int	Laundry Boiler Room/G	Old Laundry Boiler Room	Rope seal around inside of electric box Small Amounts	Sampled	Rope	No Visible	Encapsulated Textile/Paper	No Asbestos Detected	Non asbestos	0	0	0
1077922/0274	Condition Monitoring Survey	Int	Laundry Boiler Room/G	Old Laundry Boiler Room	Residue lagging Small Amounts	Sampled	Debris	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/0275	Condition Monitoring Survey	Int	Laundry Boiler Room/G	Old Laundry Boiler Room	Rope cloth Small Amounts	Sampled	Rope	No Visible	Encapsulated Textile/Paper	No Asbestos Detected	Non asbestos	0	0	0
1077922/0276	Condition Monitoring Survey	Int	Laundry Boiler Room/G	Old Laundry Boiler Room	Residue lagging Small Amounts	Sampled	Debris	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/0277	Condition Monitoring Survey	Int	Laundry Boiler Room/G	Old Laundry Boiler Room	Lagging residue Small Amounts	Sampled	Debris	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/0278	Condition Monitoring Survey	Int	Laundry Boiler Room/G	Old Laundry Boiler Room	Flange gaskets Small Amounts	Sampled	Vinyl	No Visible	Encapsulated Textile/Paper	No Asbestos Detected	Non asbestos	0	0	0
1077922/0279	Condition Monitoring Survey	Int	Laundry Boiler Room/G	Old Laundry Boiler Room	Debris Small Amounts	Sampled	Debris	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0280	Condition Monitoring Survey	Int	Laundry Boiler Room/G	Old Laundry Boiler Room	Lagging residue Small Amounts	Sampled	Debris	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/0281	Condition Monitoring Survey	Int	Laundry Boiler Room/G	Old Laundry Boiler Room	Debris Small Amounts	Sampled	Debris	Visible Debris	Debris	No Asbestos Detected	Non asbestos	0	0	0
1077922/0282	Condition Monitoring Survey	Int	Laundry Boiler Room/G	Tank room	Bitumen adhesive Small Amounts	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0283	Condition Monitoring Survey	Ext	Laundry Boiler Room/G	Front entrance	Bitumen membrane 50.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0284	Condition Monitoring Survey	Int	St Tydfils Laundry Store/G	Store Ceiling	Insulating panel 50.0m ²	Sampled	Insulating Board	Low	Painted/Encapsulated Board	Amosite	Low	6	2	8
1077922/0285	Condition Monitoring Survey	Int	St Tydfils Laundry Store/G	Store Floor	Beige tile and bitumen Small Amounts	Sampled	Vinyl	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	3	6
1077922/0286	Condition Monitoring Survey	Int	St Tydfils Laundry Store/G	Soffit to side of building Soffit	Insulating panels 25.0m Run	Sampled	Insulating Board	Low	Unsealed Board	Amosite	Medium	7	2	9
1077922/0287	Condition Monitoring Survey	Int	St Tydfils Laundry Store/G	Back of building	Broken board Small Amounts	Sampled	Debris	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/0288	Condition Monitoring Survey	Int	St Tydfils Laundry Store/G	Front of building	Bitumen membrane 50.0m Run	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0289	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Waiting space GF33	Off white linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0290	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Office/reception GF32	Green linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0291	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Sisters office GF34	Green linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0292	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Sisters office GF34 Ceiling void underneath RSJ	Slate packer Small Amounts	Sampled	Cement	Low	Unsealed Cement	Chrysotile	Very Low	4	4	8
1077922/0293	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Corridor GF39	Off white linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0294	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Wheel chairs GF35	Off white linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0295	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Wc GF11	Brown mottle linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0296	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Sluice GF29 Underside of sink	Acoustic pads 2 Items	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0297	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Sluice GF29	Beige linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0298	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Switch Room GF38	Infill panel Small Amounts	Sampled	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0299	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Clothes store GF37	Off white linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0300	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Ward pantry GF36 Underside of sink	Bitumen pads 2 Items	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0301	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Ward pantry GF36	Acoustic pads Small Amounts	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0302	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Corridor GF38	Off white linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0303	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Corridor GF38	Paint 10.0m ²	Sampled	Other	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0304	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Staff wc GF12	Off white linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0305	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Wc GF11	Beige linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0306	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Clean utility GF28 Underside of sink	Acoustic pad 1 Item	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0307	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Wc GF11	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0308	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Corridor GF37	Off white linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0309	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Vestibule GF31	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0310	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Day room GF40	Off white linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0311	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Day room GF40 Underside of sink	Acoustic pad 2 Items	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0312	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Day room GF40 Ceiling void	Ceiling void N/A	Presumed Asbestos	Insulating Board	No Visible	N/A	Asbestos	Low	5	0	5
1077922/0313	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Day room GF40	Felt membrane 50.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0314	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Office GF 49	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0315	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Lobby GF 50	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0316	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Remedial therapist GF47	Purple linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0317	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Wc GF42	Brown mottle•• linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0318	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Wc GF48	Brown mottle•• linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0319	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store GF43	Light green linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0320	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store GF44	Light green linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0321	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Corridor GF50	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0322	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Television room GF41	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0323	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Treatment room GF09	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0324	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Office GF10	Purple linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0325	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	ADL kitchen GF08 Underside of sink	Acoustic pads 2 Items	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0326	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	ADL kitchen GF08 Underside of sink	Acoustic pads 2 Items	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0327	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	ADL bathroom GF07	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0328	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Bathroom GF02	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0329	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Corridor GF04	Off white linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0330	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Treatment room GF01	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0331	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Physiotherapy GF06	Beige linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0332	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Treatment GF27	Off white linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0333	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Corridor GF58	Off white linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0334	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store GF26	Off white linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0335	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Sub-waiting GF14/25	Off white linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0336	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Examination 4 GF15	Beige linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0337	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Recovery GF24	Off white linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0338	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Consulting GF23	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0339	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Dental GF22	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0340	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Utility/laundry GF21 Underside of sink	Acoustic pad 1 Item	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0341	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Utility/laundry GF21	Brown mottle•• linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0342	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Clinical waste GF15	Beige linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0343	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store GF15	Beige linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0344	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Examination 2 GF17	Beige linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0345	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Examination 3 GF16	Beige linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0346	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Treatment GF13	Green linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0347	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 01	White panels 50.0m ²	Sampled	Insulating Board	Visible Debris	Unsealed Board	Asbestos Removed	Non asbestos	0	0	0
1077922/0348	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 01	Debris Small Amounts	Sampled	Debris	Visible Debris	Debris	No Asbestos Detected	Non asbestos	0	0	0
1077922/0349	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 03	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0350	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 02	paper Small Amounts	Sampled	Paper	Low	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0351	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 02	No Access N/A	No Access - Presumed Asbestos	Select Product	No Visible	N/A	No Access	Very Low	3	0	3
1077922/0352	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Painters 67	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0353	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Electricians workshop 75	Tin of sealant with asbestos fibers in Small Amounts	Sampled	Other	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0354	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 71	Fire blanket 1 Item	Sampled	Cloth	No Visible	Encapsulated Textile/Paper	Asbestos Removed	Non asbestos	0	0	0
1077922/0355	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Workshop 75	Fuse flash guard Small Amounts	Sampled	Cloth	No Visible	Encapsulated Textile/Paper	Asbestos Removed	Non asbestos	0	0	0
1077922/0356	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Electricians workshop 75	Insulating tiles Small Amounts	Sampled	Insulating Board	Medium	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0357	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 71	Roof slates Small Amounts	Sampled	Cement	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0358	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 72	Coiled rope 50.0m Run	Sampled	Rope	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0359	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 72	Coiled rope 50.0m Run	Sampled	Rope	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0360	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 72	Fire blanket Small Amounts	Sampled	Cloth	No Visible	Encapsulated Textile/Paper	Asbestos Removed	Non asbestos	0	0	0
1077922/0361	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 72	Rolled up flooring 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0362	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 72	Red rolled up flooring product 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0363	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 72	Pink floor material 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0364	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 72	In a tin, flaked particles Small Amounts	Sampled	Other	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0365	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 72	Tins of flaked heat resistant material Small Amounts	Presumed Asbestos	Other	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0366	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 69 Floor	Cream tile and bitumen 50.0m ²	Sampled	Vinyl	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	5	8
1077922/0367	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Store 68 Floor	Cream tile and bitumen 50.0m ²	Visually Similar To	Vinyl	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	5	8
1077922/0368	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Mess room 76 Under window	Cream painted panel 10.0m ²	Sampled	Cement	No Visible	Painted/Sealed Cement	Chrysotile	Very Low	2	3	5
1077922/0369	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Mess room 76	Flange gasket debris Small Amounts	Sampled	Gasket	Visible Debris	Debris	No Asbestos Detected	Non asbestos	0	0	0
1077922/0370	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Mess room 76	Grey tile 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0371	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Mess room 76 Wall	Electric boxes N/A	Presumed Asbestos	Rope	No Visible	N/A	Asbestos	Low	5	0	5
1077922/0372	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Lockers 75	Grey tile 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0373	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Wc/shower 74	Grey tile 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0374	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Wc/shower 74 Floor	Flange gaskets Small Amounts	Sampled	Gasket	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/0375	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Lockers 73 Ceiling	Paint 50.0m ²	Sampled	Textured Coating	Visible Debris	Painted/Sealed Cement	Chrysotile	Low	5	5	10
1077922/0376	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77	Rope in wax covering Small Amounts	Sampled	Rope	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/0377	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77	Flange gasket Small Amounts	Sampled	Gasket	No Visible	Encapsulated Textile/Paper	No Asbestos Detected	Non asbestos	0	0	0
1077922/0378	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77 Pipework behind calorifier 2	Flange gasket Small Amounts	Sampled	Gasket	No Visible	Encapsulated Textile/Paper	Chrysotile	Low	5	3	8
1077922/0379	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77	Flange gasket Small Amounts	Sampled	Gasket	No Visible	Encapsulated Textile/Paper	No Asbestos Detected	Non asbestos	0	0	0
1077922/0380	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77	Lagging debris Small Amounts	Sampled	Thermal Lagging	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/0381	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77	Lagging debris Small Amounts	Sampled	Thermal Lagging	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/0382	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77	Left over mmmf from pipe Small Amounts	Sampled	Thermal Lagging	High	Unsealed Spray/Lagging/Textile	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0383	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77	Gasket material Small Amounts	Sampled	Gasket	No Visible	Encapsulated Textile/Paper	Asbestos Removed	Non asbestos	0	0	0
1077922/0384	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77	Debris Small Amounts	Sampled	Debris	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/0385	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77	Debris Small Amounts	Sampled	Debris	Visible Debris	Debris	No Asbestos Detected	Non asbestos	0	0	0
1077922/0386	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77	Debris on pipe work Small Amounts	Sampled	Debris	Visible Debris	Debris	No Asbestos Detected	Non asbestos	0	0	0
1077922/0387	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77 Wall around pipe	Putty seal around pipe Small Amounts	Sampled	Mastic	No Visible	Reinforced - Composite Materials	Chrysotile	Very Low	2	2	4
1077922/0388	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77	Flange gasket to redundant pipe work Small Amounts	Sampled	Gasket	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/0389	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77 Wall	Electrical boxes N/A	Presumed Asbestos	Rope	No Visible	N/A	Asbestos	Low	5	0	5
1077922/0390	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77 Metal clad pipework	Pipe work N/A	Presumed Asbestos	Paper	No Visible	N/A	Asbestos	Low	5	4	9
1077922/0391	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77 Wall void	No Access N/A	Presumed Asbestos	Other	No Visible	N/A	Asbestos	Low	6	2	8
1077922/0392	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Calorifier 77 Ceiling	No Access N/A	Presumed Asbestos	Other	No Visible	N/A	Asbestos	Low	6	2	8
1077922/0393	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78 Door header	Infill panel Small Amounts	Sampled	Cement	No Visible	Painted/Sealed Cement	Chrysotile	Very Low	2	2	4
1077922/0394	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78 Pipe at back of boiler one	Rope seal Small Amounts	Sampled	Rope	No Visible	Encapsulated Textile/Paper	Chrysotile	Low	5	3	8
1077922/0395	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78 Pipe at back of boiler two	Rope seal Small Amounts	Visually Similar To	Rope	No Visible	Encapsulated Textile/Paper	Chrysotile	Low	5	3	8
1077922/0396	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78	Rope seal Small Amounts	Sampled	Rope	No Visible	Encapsulated Textile/Paper	No Asbestos Detected	Non asbestos	0	0	0
1077922/0397	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78	Pink flange gasket Small Amounts	Sampled	Gasket	No Visible	Encapsulated Textile/Paper	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0398	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78 Boiler one veiwing eye	White seal Small Amounts	Sampled	Gasket	No Visible	Encapsulated Textile/Paper	Chrysotile	Low	5	3	8
1077922/0399	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78 Front of boiler 2 around viewing eye	White seal Small Amounts	Visually Similar To	Gasket	No Visible	Encapsulated Textile/Paper	Chrysotile	Low	5	3	8
1077922/0400	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78 Front of boiler three around veiwing panel	White seal Small Amounts	Visually Similar To	Gasket	No Visible	Encapsulated Textile/Paper	Chrysotile	Low	5	3	8
1077922/0401	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78 Bottom left hand corner of boiler room	Flange gasket Small Amounts	Sampled	Gasket	Low	Unsealed Spray/Lagging/Textile	Chrysotile	Medium	7	4	11
1077922/0402	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78 Front of boiler three	Cream flange gasket Small Amounts	Sampled	Gasket	No Visible	Encapsulated Textile/Paper	Chrysotile	Low	5	3	8
1077922/0403	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78	Debris Small Amounts	Sampled	Debris	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/0404	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78 Duct through wall	Debris Small Amounts	Sampled	Debris	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/0405	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78 Door header	Infill panel Small Amounts	Visually Similar To	Cement	Medium	Painted/Sealed Cement	Chrysotile	Very Low	4	3	7
1077922/0406	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78	Flange gaskets Small Amounts	Sampled	Gasket	No Visible	Encapsulated Textile/Paper	Asbestos Removed	Non asbestos	0	0	0
1077922/0407	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78	White flange gasket Small Amounts	Sampled	Gasket	No Visible	Encapsulated Textile/Paper	No Asbestos Detected	Non asbestos	0	0	0
1077922/0408	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78	Flange gasket Small Amounts	Sampled	Gasket	No Visible	Encapsulated Textile/Paper	Asbestos Removed	Non asbestos	0	0	0
1077922/0409	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78	Big pink flange gaskets Small Amounts	Sampled	Gasket	No Visible	Encapsulated Textile/Paper	Asbestos Removed	Non asbestos	0	0	0
1077922/0410	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78 Sky lights	Boiler house Small Amounts	Presumed Asbestos	Other	No Visible	N/A	Asbestos	Low	6	2	8
1077922/0411	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78	Pipe ducts from boilers N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0412	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78 Wall	Electric boxes N/A	Presumed Asbestos	Rope	No Visible	N/A	Asbestos	Low	5	0	5

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0413	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78 Pipework	Pipe work clad in metal N/A	Presumed Asbestos	Paper	No Visible	N/A	Asbestos	Low	5	3	8
1077922/0414	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78	Debris Small Amounts	Sampled	Debris	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/0415	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Electricians workshop 75 Wall	Electric box N/A	Presumed Asbestos	Insulating Board	Low	Unsealed Board	Asbestos	Medium	8	4	12
1077922/0416	Condition Monitoring Survey	Int	St Tydfils, Main Boiler House/G	Boiler house 78 Back wall	Old coal store N/A	Presumed Asbestos	Thermal Lagging	No Visible	N/A	Asbestos	Low	6	3	9
1077922/0417	Condition Monitoring Survey	Int	St Tydfils, Hafod House/G	Kitchen 006	Grey floor tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0418	Condition Monitoring Survey	Int	St Tydfils, Hafod House/G	Kitchen 006	Black vinyl Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0419	Condition Monitoring Survey	Int	St Tydfils, Hafod House/G	Kitchen 006	Beige tile and bitumen Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0420	Condition Monitoring Survey	Int	St Tydfils, Hafod House/G	Kitchen 006	Rope textile seal Small Amounts	Sampled	Rope	No Visible	Encapsulated Textile/Paper	No Asbestos Detected	Non asbestos	0	0	0
1077922/0421	Condition Monitoring Survey	Int	St Tydfils, Hafod House/G	Kitchen 006	Cement compound Small Amounts	Sampled	Cement	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0422	Condition Monitoring Survey	Int	St Tydfils, Hafod House/G	Kitchen 006	Acoustic pads 2 Items	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0423	Condition Monitoring Survey	Int	St Tydfils, Hafod House/G	Lounge 005	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0424	Condition Monitoring Survey	Int	St Tydfils, Hafod House/G	Flat 1 003	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0425	Condition Monitoring Survey	Int	St Tydfils, Hafod House/G	Lobby 001	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0426	Condition Monitoring Survey	Int	St Tydfils, Hafod House/G	Hall 002	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0427	Condition Monitoring Survey	Int	St Tydfils, Hafod House/G	Wc 004	Beige mottled linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0428	Condition Monitoring Survey	Int	St Tydfils, Hafod House/G	Kitchen 006	Felt membrane 50.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0429	Condition Monitoring Survey	Int	St Tydfils, Hafod House/F 1	Flat 2 102	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0430	Condition Monitoring Survey	Int	St Tydfils, Hafod House/F 1	Flat 3 104	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0431	Condition Monitoring Survey	Int	St Tydfils, Hafod House/G	Flat 4 105	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0432	Condition Monitoring Survey	Int	St Tydfils, Hafod House/F 1	Stair case	Black vinyl 16 Items	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0433	Condition Monitoring Survey	Int	St Tydfils, Hafod House/F 1	Landing 101	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0434	Condition Monitoring Survey	Int	St Tydfils, Hafod House/F 1	Bathroom 103	Blue patterned linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0435	Condition Monitoring Survey	Int	St Tydfils, Hafod House/F 1	Attic space, via bathroom 103	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0436	Condition Monitoring Survey	Ext	St Tydfils, Hafod House/G	Boiler 007	Felt membrane 10.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0437	Condition Monitoring Survey	Ext	St Tydfils, Hafod House/G	Kitchen 006 Roof	Roof slates 50.0m ²	Sampled	Cement	Low	Unsealed Cement	Chrysotile	Very Low	4	2	6
1077922/0438	Condition Monitoring Survey	Int	St Tydfils, Psychology Therapy Centre/G	Lobby pt01	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0439	Condition Monitoring Survey	Int	St Tydfils, Psychology Therapy Centre/G	Disabled wc pt02	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0440	Condition Monitoring Survey	Int	St Tydfils, Psychology Therapy Centre/G	Kitchen pt03	Acoustic pad Small Amounts	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0441	Condition Monitoring Survey	Int	St Tydfils, Psychology Therapy Centre/G	Office 1 pt04	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0442	Condition Monitoring Survey	Int	St Tydfils, Psychology Therapy Centre/G	Main reception pt09	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0443	Condition Monitoring Survey	Int	St Tydfils, Psychology Therapy Centre/G	Office 2 pt05	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0444	Condition Monitoring Survey	Int	St Tydfils, Psychology Therapy Centre/G	Office pt06	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0445	Condition Monitoring Survey	Int	St Tydfils, Psychology Therapy Centre/G	Office 4 pt07	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0446	Condition Monitoring Survey	Int	St Tydfils, Psychology Therapy Centre/G	Office 5 pt08	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0447	Condition Monitoring Survey	Int	St Tydfils, Psychology Therapy Centre/G	All roof area Roof space	Roof area entry point N/A	Presumed Asbestos	Bitumen	No Visible	N/A	Asbestos	Very Low	4	0	4
1077922/0448	Condition Monitoring Survey	Ext	St Tydfils, Psychology Therapy Centre/G	Above main reception pt09	Roof slate 50.0m ²	Sampled	Cement	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0449	Condition Monitoring Survey	Int	St Tydfils, Gardeners Shed/G	Gardeners shed 01 Floor	Slate coloured floor covering 50.0m ²	Sampled	Vinyl	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	5	8
1077922/0450	Condition Monitoring Survey	Int	St Tydfils, Gardeners Shed/G	Gardeners shed 01	Green floor covering 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0451	Condition Monitoring Survey	Ext	St Tydfils, Gardeners Shed/G	Gardeners shed 01 Wall	Expansion joints 50.0m Run	Sampled	Mastic	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	2	5
1077922/0452	Condition Monitoring Survey	Ext	St Tydfils, Gardeners Shed/G	Roof Roof	Cement corrugated roof 50.0m ²	Sampled	Cement	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	2	5
1077922/0453	Condition Monitoring Survey	Ext	St Tydfils, Gardeners Shed/G	Gardeners shed 01 Edge and centre of roof	Corner covering 5.00m ²	Sampled	Cement	Low	Unsealed Cement	Chrysotile	Very Low	4	1	5
1077922/0454	Condition Monitoring Survey	Ext	St Tydfils, Gardeners Shed/G	Gardeners shed 01 Walls at either end	Corrugated wall cover 50.0m ²	Sampled	Cement	Low	Unsealed Cement	Chrysotile	Very Low	4	2	6
1077922/0455	Condition Monitoring Survey	Ext	St Tydfils, Gardeners Shed/G	Gardeners shed 01 Wall	Cement rain water goods 25.0m Run	Sampled	Cement	Low	Unsealed Cement	Chrysotile	Very Low	4	2	6

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0456	Condition Monitoring Survey	Ext	St Tydfils, Gardeners Shed/G	Gardeners shed 01 Wall	Rain water down pipe 6.00m Run	Sampled	Cement	Low	Unsealed Cement	Chrysotile	Very Low	4	2	6
1077922/0457	Condition Monitoring Survey	Int	St Tydfils, Medical Store/G	Medical gases 01	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0458	Condition Monitoring Survey	Int	St Tydfils, Medical Store/G	Oxygen store 02	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0459	Condition Monitoring Survey	Int	St Tydfils, Medical Store/G	Cylinder store 03	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0460	Condition Monitoring Survey	Ext	St Tydfils, Medical Store/G	Externals	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0461	Condition Monitoring Survey	Int	St Tydfils, Body Store/G	Fridge 1	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0462	Condition Monitoring Survey	Int	St Tydfils, Body Store/G	Fridge 2	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0463	Condition Monitoring Survey	Int	St Tydfils, Body Store/G	Body store 03	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0464	Condition Monitoring Survey	Int	St Tydfils, Body Store/G	Wc 06	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0465	Condition Monitoring Survey	Int	St Tydfils, Body Store/G	Post mortem 04	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0466	Condition Monitoring Survey	Int	St Tydfils, Body Store/G	Changing room 05	Red floor covering 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0467	Condition Monitoring Survey	Int	St Tydfils, Body Store/G	Viewing 02	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0468	Condition Monitoring Survey	Int	St Tydfils, Body Store/G	Lobby/waiting 01	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0469	Condition Monitoring Survey	Int	St Tydfils, Body Store/G	Attic space	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0470	Condition Monitoring Survey	Ext	St Tydfils, Body Store/G	Externals	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0471	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Female wc 003 Floor	Blue linoleum 50.0m ²	Sampled	Vinyl	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	3	6
1077922/0472	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Female wc 003	Blue melamine 50.0m ²	Sampled	Plastics	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0473	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Cupboard 004 Floor	Blue linoleum 4.00m ²	Visually Similar To	Vinyl	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	3	6

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0474	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Lobby 002 Floor	Blue linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	Chrysotile	Very Low	2	3	5
1077922/0475	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Lobby 002 Step	Black vinyl nosings 2 Items	Sampled	Plastics	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	2	5
1077922/0476	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Male wc 005 Floor	Blue linoleum 50.0m ²	Visually Similar To	Vinyl	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	3	6
1077922/0477	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Male wc 005	Blue melamine 2.00m ²	Visually Similar To	Plastics	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0478	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Stairs GF45	Grey tile 10.0m ²	Sampled	Vinyl	Low	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0479	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 1 001	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0480	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 3 008 Door frame	Slate packers Small Amounts	Sampled	Cement	Medium	Unsealed Cement	Chrysotile	Low	5	2	7
1077922/0481	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 2 007	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0482	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 4 010	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0483	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 5 011	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0484	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 6 012	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0485	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Corridor 1 006	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0486	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Wc 017 Wall and floor	Black cistern 1 Item	Sampled	Plastics	Visible Debris	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0487	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 7 014	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0488	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 9 016	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0489	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Corridor 3 013	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0490	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 8 015 Floor	Green vinyl tiles and bitumen Small Amounts	Sampled	Vinyl	Medium	Reinforced - Composite Materials	Chrysotile	Very Low	4	3	7
1077922/0491	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 8 015 Floor	Beige tile and bitumen 50.0m ²	Sampled	Vinyl	Medium	Reinforced - Composite Materials	Chrysotile	Very Low	4	3	7

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0492	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Corridor 2 009 Ceiling	Slate packing Small Amounts	Sampled	Cement	No Visible	Unsealed Cement	Chrysotile	Very Low	3	2	5
1077922/0493	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Corridor 2 009 Redundant pipework	Flange gasket Small Amounts	Sampled	Gasket	Low	Encapsulated Textile/Paper	Chrysotile	Low	6	2	8
1077922/0494	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Corridor 4 018 Pipework	Flange gasket Small Amounts	Sampled	Gasket	No Visible	Encapsulated Textile/Paper	Chrysotile	Low	5	3	8
1077922/0495	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Stairwell 019 Steps	White nosings 46 Items	Sampled	Vinyl	Low	Reinforced - Composite Materials	Amosite	Very Low	4	2	6
1077922/0496	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Stairwell 019 Steps	Green tile and bitumen 50.0m ²	Sampled	Vinyl	Visible Debris	Reinforced - Composite Materials	Chrysotile	Low	5	3	8
1077922/0497	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 10 020	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0498	Condition Monitoring Survey	Ext	St Tydfils Day Care Unit/B	Court yard	Bitumen wrap 10.0m ²	Sampled	Cloth	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0499	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Stairs GF	Beige linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0500	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 13 024	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0501	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 12 023	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0502	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Corridor 5 022 Ceiling	Slate packing Small Amounts	Visually Similar To	Cement	No Visible	Unsealed Cement	Chrysotile	Very Low	3	2	5
1077922/0503	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 11 021	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0504	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Lift	Redundant lift N/A	No Access - Presumed Asbestos	Select Product	No Visible	N/A	No Access	Very Low	3	0	3
1077922/0505	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 14 026 Pipework inside sterilizer	Rope 10.0m Run	Sampled	Rope	Medium	Unsealed Spray/Lagging/Textile	Asbestos Removed	Non asbestos	0	0	0
1077922/0506	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 14 026 Sterilizer drum	Card wrap 2.00m ²	Sampled	Paper	No Visible	Encapsulated Textile/Paper	Chrysotile	Low	5	3	8
1077922/0507	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 14 026 Inside sterilizer drum	Flange gasket Small Amounts	Sampled	Gasket	Low	Encapsulated Textile/Paper	Chrysotile	Low	6	2	8
1077922/0508	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 15 028 Pipework	Flange gasket Small Amounts	Sampled	Gasket	No Visible	Encapsulated Textile/Paper	Chrysotile	Low	5	3	8

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0509	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Age concern office 54	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0510	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Office 52	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0511	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Corridor 53	Beige linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0512	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Staff wc 51	Beige linoleum 4.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0513	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Stairs 53a	Beige linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0514	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Office 53b	Dark red tile 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0515	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Office 53b	Red tile 50.0m ²	Sampled	Vinyl	Medium	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0516	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Roof space FF28	Roof felt 50.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0517	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Craft room FF10 Underside of sink	Acoustic pad 1 Item	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0518	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Craft room FF10	Grey linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0519	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Workshop FF14	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0520	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Workshop FF14 Underside of sink	Acoustic pad 1 Item	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0521	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Workshop FF14	Insulating panel Small Amounts	Sampled	Cement	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0522	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Lobby FF20	Beige linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0523	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	OT store FF11	Beige linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0524	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Male wc FF12	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0525	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Female wc FF12	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0526	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Corridor 6 025	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0527	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Counseling room FF09	Beige linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0528	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Lobby FF19	Beige linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0529	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Physio store FF17	Beige linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0530	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Woodwork FF15 Underside of sink	Acoustic pad 1 Item	Presumed Asbestos	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0531	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Relaxation/group room FF07	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0532	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Corridor FF16	Beige linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0533	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Lift FF01a	No Access N/A	No Access - Presumed Asbestos	Select Product	No Visible	N/A	No Access	Very Low	3	0	3
1077922/0534	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Games room FF02	Blue linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0535	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Gymnasium FF04	Blue linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0536	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Staff changing FF05	Blue linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0537	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Office FF06	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0538	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Wax therapy FF03	Blue linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0539	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	ADL kitchen FF16	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0540	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Wc FF08	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0541	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Stairs GF04 Steps	White nosings 36 Items	Sampled	Vinyl	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	2	5
1077922/0542	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Stairs GF04	Brown linoleum and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0543	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Stairs FF21	Green linoleum and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0544	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Lobby/stairs GF06	White nosing Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0545	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Lobby/stairs GF06	Dark green linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0546	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Lobby/stairs GF06	Pale green linoleum 10.0m Run	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0547	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Lift GF08a	No Access N/A	No Access - Presumed Asbestos	Select Product	No Visible	N/A	No Access	Very Low	3	0	3
1077922/0548	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Ward SF20 Floor	White tile Small Amounts	Sampled	Vinyl	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	2	5
1077922/0549	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Loft	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0550	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Workshop SF26 Floor, back half of room	Red linoleum 50.0m ²	Sampled	Vinyl	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	3	6
1077922/0551	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Store SF27	Red tile 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0552	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Workshop SF25 Floor	Grey linoleum 50.0m ²	Sampled	Vinyl	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	3	6
1077922/0553	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Wc SF24	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0554	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Lobby SF21	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0555	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Wc SF23	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0556	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Store SF22 Floor	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	3	6
1077922/0557	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Store SF22 Inside sluice machine	Flange gaskets Small Amounts	Sampled	Gasket	Low	Reinforced - Composite Materials	Chrysotile	Very Low	4	3	7
1077922/0558	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Kitchen SF29	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0559	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Store SF30	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0560	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Store SF19	Grey tile 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0561	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Store SF28	Grey tile Small Amounts	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0562	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Corridor SF18	Blue linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0563	Condition Monitoring Survey	Ext	St Tydfils Day Care Unit/F 2	Office SF15 Stylight	Rope seal 25.0m Run	Sampled	Rope	Low	Unsealed Spray/Lagging/Textile	Chrysotile	Medium	7	2	9
1077922/0564	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Corridor SF18	Bitumen membrane 50.0m Run	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0565	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Office SF02	Cream linoleum 50.0m ²	Sampled	Vinyl	Low	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0566	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Office SF03	Pale grey linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0567	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Office SF17	Pale grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0568	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Office SF16	Pale grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0569	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Office SF15	Pale grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0570	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Staff changing SF12	Pale grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0571	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Office SF10	Pale grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0572	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Wc SF08/09	Pale grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0573	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Office SF04	Pale grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0574	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Lobby SF07	Blue linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0575	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Store SF05	Blue linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0576	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Lobby SF08	Blue linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0577	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Office SF03	Blue linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0578	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Wc SF08/09	Blue linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0579	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Office SF15	Rope Small Amounts	Sampled	Rope	No Visible	Encapsulated Textile/Paper	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0580	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	WC SF13	Pale grey floor tiles 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0581	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	WC SF13	Black cistern 1 Item	Sampled	Plastics	Low	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0582	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Lift SF01a	No Access N/A	No Access - Presumed Asbestos	Select Product	No Visible	N/A	No Access	Very Low	3	0	3
1077922/0583	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Flat roof Inner roof	Flat roof N/A	Presumed Asbestos	Bitumen	Low	Reinforced - Composite Materials	Asbestos	Low	5	1	6
1077922/0584	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 1	Stairs FF22	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0585	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Utility SF33	Red tile 50.0m ²	Sampled	Vinyl	Medium	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0586	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Utility SF37	Red tile 50.0m ²	Visually Similar To	Vinyl	Medium	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0587	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Utility SF37	Bitumen paste Small Amounts	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0588	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Corridor SF32 Floor	Dark green tile 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0589	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Corridor SF32 Floor	Cream floor tile Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0590	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Wc SF34 Floor	Dark green tile 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0591	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Corridor SF32 Electric box	Mill board Small Amounts	Sampled	Millboard	No Visible	Unsealed Board	Asbestos Removed	Non asbestos	0	0	0
1077922/0592	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Stairs SF31 Floor	Dark green tile 50.0m ²	Visually Similar To	Vinyl	Medium	Reinforced - Composite Materials	Chrysotile	Very Low	4	3	7
1077922/0593	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Tank room SF36	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0594	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/F 2	Office SF36	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0595	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Mess room FF24 Floor	Beige linoleum and bitumen 50.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0596	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Lobby FF26	Beige linoleum and bitumen 10.0m ²	Visually Similar To	Bitumen	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0597	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Stairs FF27	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0598	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Office FF25	No Asbestos N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0599	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Store FF30 Floor	Green tiles and bitumen 10.0m ²	Sampled	Vinyl	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/0600	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Carpenters workshop FF29	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0601	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Machine room FF31 Wall	Electrical Boxes N/A	Presumed Asbestos	Rope	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/0602	Condition Monitoring Survey	Int	St Tydfils, Workshops/G	Store 65	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0603	Condition Monitoring Survey	Int	St Tydfils, Workshops/G	Store 66	Bitumen roll of roof felt 10.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0604	Condition Monitoring Survey	Int	St Tydfils, Workshops/G	Store 66	Roof slate 10.0m ²	Sampled	Cement	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0605	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Store FF32 Roof/ceiling in centre of room	Cement profiled sheets 10.0m ²	Presumed Asbestos	Cement	Low	Unsealed Cement	Asbestos	Low	6	2	8
1077922/0606	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Store FF33 Floor	Deep grey tile and bitumen 50.0m ²	Sampled	Vinyl	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0607	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Store FF35	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0608	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Office FF36 Floor	Dark brown tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/0609	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Office FF36	Roof slates Small Amounts	Sampled	Cement	No Visible	Reinforced - Composite Materials	Asbestos Removed	Non asbestos	0	0	0
1077922/0610	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Store FF37 Floor	Dark brown tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/0611	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Store FF34	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0612	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Store FF32	Lagging debris Small Amounts	Sampled	Debris	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/0613	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Store FF32	Insulating board 10.0m ²	Sampled	Insulating Board	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0614	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Mezzanine floor 1 Wall	Lagging 10.0m Run	Sampled	Thermal Lagging	High	Encapsulated Lagging/Spray	Asbestos Removed	Non asbestos	0	0	0
1077922/0615	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Kitchen T5103	Acoustic pads Small Amounts	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0616	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Office T5104	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0617	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Office T5105	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0618	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Office T5106	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0619	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Office T599	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0620	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Store T5102	Blue linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0621	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Store T5101	Blue linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0622	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Office T5100	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0623	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Corridor T5112	Grey linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0624	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Corridor T5112	Black skirting board 50.0m Run	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0625	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Staircase T598	Black skirting board 10.0m Run	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0626	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Staircase T598	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0627	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Payroll team leader T5110	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0628	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Corridor T5111	Black skirting board 50.0m Run	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0629	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Corridor T5111	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0630	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Female wc T5109	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0631	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Male wc T5107	Blue linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0632	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Male wc T5107	Black skirting board 25.0m Run	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0633	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Payroll T5108	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0634	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Loft	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0635	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Store T586	Dark grey linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0636	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Store T586	Light grey linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0637	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Store T586	Black skirting 50.0m Run	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0638	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Store T585	Blue linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0639	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Store T585	Black skirting 25.0m Run	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0640	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Office T587	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0641	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Office T588	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0642	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Office T589	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0643	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Office T590	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0644	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Office T584	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0645	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Office T583	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0646	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Office T596	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0647	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Office T595	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0648	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Office T594	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0649	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Office T593	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0650	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Office T592	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0651	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Corridor T597	Black skirting 50.0m Run	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0652	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Corridor T597	Light grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0653	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Female wc T591	Black skirting 50.0m Run	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0654	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Female Wc T591	Blue linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0655	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Staircase T582	Black skirting 10.0m Run	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0656	Condition Monitoring Survey	Int	St Tydfils Main Building/F 2	Staircase T582	Light grey linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0657	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Lobby T476	Brown tiles 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0658	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Assisted shower and wc T444	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0659	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Wc T443	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0660	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Staff wc T446	Cream tile and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0661	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	6 bed ward T445	Brown tiles 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0662	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	6 bed ward T445	Pink tiles Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0663	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	6 bed ward T445	Brown tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0664	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	6 bed ward T445	Pale cream tiles Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0665	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	6 bed ward T445	Tan coloured tiles at door entrance Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0666	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T477	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0667	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Clean utility T447 Underside of sink	Acoustic pad 1 Item	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0668	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Equipment store T449	Cream tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0669	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T482a	Cream tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0670	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Single bed ward T474	Brown tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0671	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Single bed ward T475	Brown tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0672	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	5 bed ward T469	Brown tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0673	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	5 bed ward T468	Brown tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0674	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Assisted bath and wc T470	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0675	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Assisted wc T471	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0676	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Wc T473	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0677	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	First floor ceiling voids	No Access N/A	No Access - Presumed Asbestos	Select Product	No Visible	N/A	No Access	Very Low	3	0	3
1077922/0678	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Nurse station T448	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0679	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Cupboard	Cream floor tiles and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0680	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Dirty utility T450	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0681	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T478	White board 10.0m ²	Sampled	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0682	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	4 bed ward T452	Brown tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0683	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Laundry T454	Cream floor tiles and bitumen 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0684	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Clinical waste T467	Grey tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0685	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Assisted bath and wc T453	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0686	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Single bed ward T456	Brown tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0687	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Single bed ward T457	Brown tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0688	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Ward pantry T466	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0689	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T480	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0690	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T479	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0691	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Wheel chair store T451	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0692	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Lobby T481	Brown tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0693	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Lobby T481	Insulating tiles 50.0m ²	Sampled	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0694	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Staircase T483	Brown nosings 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0695	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Staircase T483	Insulating tiles 50.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0696	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Lobby T481	Above fixed tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0697	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Staircase T483	Above fixed tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0698	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Lobby T482	Cream floor tiles and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0699	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Doctor T463	Cream floor tiles and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0700	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Lobby T482	Pale cream tiles Small Amounts	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0701	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Quiet room T458	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0702	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Sister T462	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0703	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Dining day room T459	Brown tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0704	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Assisted wc T460	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0705	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Assisted wc T461	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0706	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T581	Grey specked linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0707	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Domestic T465	Black vinyl strip Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0708	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Domestic T465	Grey specked linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0709	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T464	Brown tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0710	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Treatment room T559	Blue tiles 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0711	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Treatment room T559 Underside of sink	Acoustic pads 3 Items	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0712	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T558 Ceiling void	Cement tile used as packing Small Amounts	Sampled	Cement	Low	Painted/Sealed Cement	Chrysotile	Very Low	3	4	7
1077922/0713	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T558	Insulating tiles 10.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0714	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Kitchen T563 Underside of sink	Acoustic pads 2 Items	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0715	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Wc T560	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0716	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Consulting room T562	Above fixed ceiling tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0717	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T577	Above fixed ceiling tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0718	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T578	Above fixed ceiling tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0719	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Physiotherapy	Above fixed ceiling tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0720	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Staircase T564	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0721	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T579	Insulating tiles 50.0m ²	Sampled	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0722	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T579	Beige linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0723	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T579	Above fixed ceiling tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0724	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Female wc T568	Above fixed ceiling tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0725	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Male wc T567 Ceiling void	Slate packers Small Amounts	Sampled	Cement	Low	Unsealed Cement	Chrysotile	Very Low	4	4	8
1077922/0726	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T569	Insulating tiles 10.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0727	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T569	Beige linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0728	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T569	Above fixed ceiling tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0729	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Dish wash T573	Beige mottled linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0730	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Servery T571	Beige mottled linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0731	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Entrance to dining area	Beige mottled linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0732	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Dish wash T573	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0733	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Attic space Attic	Limited access due to height restrictions and visual restrictions N/A	Presumed Asbestos	Insulating Board	No Visible	N/A	Asbestos	Low	5	2	7
1077922/0734	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T570	Cream floor tiles and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0735	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T570	Insulating tiles 5.00m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0736	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T570	Above fixed ceiling tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0737	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Entrance to dining area	Insulating tiles 5.00m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0738	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Entrance to dining area	Above fixed ceiling tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0739	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor 1	Insulating tiles 50.0m ²	Sampled	Insulating Board	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0740	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor 1	Grey specked linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0741	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	6 bed ward T640	Grey tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0742	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Single bed ward T641	Grey tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0743	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Single bed ward	Grey tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0744	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	5 bed ward T646	Grey tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0745	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	5 bed ward T647	Grey tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0746	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Assisted bath and wc T645	Grey specked linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0747	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Assisted wc T644	Grey specked linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0748	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Wc T643	Grey specked linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0749	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T670	Cream floor tiles and bitumen adhesive 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0750	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Cupboard 1	Cream floor tiles and bitumen adhesive 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0751	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Lobby T639	Cream floor tiles and bitumen adhesive 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0752	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T639a	Cream floor tiles and bitumen adhesive 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0753	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Disabled T638	Grey specked linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0754	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Nurse station T648	Cream floor tiles and bitumen adhesive 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0755	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T671	Cream floor tiles and bitumen adhesive 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0756	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Equipment store T649	Cream floor tiles and bitumen adhesive 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0757	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Staff wc T650	Cream floor tiles and bitumen adhesive 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0758	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Clean utility T651 Underside of sink	Acoustic pads 3 Items	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	Chrysotile	Very Low	2	4	6
1077922/0759	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Clean utility T651	Brown tile 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0760	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Dirty utility T653 Underside of sink	Acoustic pads 2 Items	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0761	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Dirty utility T653	Grey specked linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0762	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Wheel chair store T652	Cream floor tiles and bitumen adhesive 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0763	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Cupboard 2	Cream floor tiles and bitumen adhesive 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0764	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Laundry T655	Cream floor tiles and bitumen adhesive 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0765	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	4 bed ward T654	Grey tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0766	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Assisted bath and wc T656	Grey specked linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0767	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Disposal T689	Grey tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0768	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T672	Cream floor tiles and bitumen adhesive 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0769	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Assisted shower and wc T657	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0770	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T673	Cream floor tiles and bitumen adhesive 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0771	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Single bed ward T658	Grey tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0772	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Single bed ward T659	Grey tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0773	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T672	Fawn coloured tile Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0774	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T673	White tile Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0775	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Ward pantry T668	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0776	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Above all areas on first floor Ceiling voids	Panels N/A	Presumed Asbestos	Insulating Board	No Visible	N/A	Asbestos	Low	5	2	7
1077922/0777	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T667	Ceiling tiles 10.0m ²	Sampled	Insulating Board	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0778	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T667	Cream floor tiles and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0779	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T667	Above fixed tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0780	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T667 Wall	Electrical Boxes N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0781	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T667	Grey specked linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0782	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T580	Beige linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0783	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Lobby T674	Beige linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0784	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Lobby T674	Ceiling tiles 10.0m ²	Visually Similar To	Insulating Board	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0785	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Lobby T674	Above fixed ceiling tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0786	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Lift	Black linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0787	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Assistant wc T662	Grey specked linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0788	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Assistant wc T661	Grey specked linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0789	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Dining/day room T663	Green tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0790	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Chapel T660	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0791	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Sister T664	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0792	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Lobby T675	Cream floor tiles and bitumen adhesive 6.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0793	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Lobby T675	White tile Small Amounts	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0794	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Ward pantry T471	Beige linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0795	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T734	White tile 50.0m ²	Sampled	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0796	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Corridor T734	Above fixed tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0797	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Loft	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0798	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Ward pantry T741	Acoustic pads Small Amounts	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0799	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Day room T749	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0800	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Disposable T737	Beige linoleum 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0801	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Disposable T737	Loose tiles Small Amounts	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0802	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T736	Beige linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0803	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store T735	Beige linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0804	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Ward T730	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0805	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Ward T730 stairs	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0806	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Sister office T739	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0807	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Bathroom T738	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0808	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	2 bed ward T729	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0809	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Staff wc T733	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0810	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Drug store T732	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0811	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Nurse station T731	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0812	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Single bed ward T728	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0813	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Single bed ward T727	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0814	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Bathroom T725	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0815	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Sluice room T726	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0816	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Wc T727a	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0817	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Loft area Loft	Panels N/A	Presumed Asbestos	Insulating Board	No Visible	N/A	Asbestos	Low	5	0	5
1077922/0818	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Reception 509	Bitumen membrane 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0819	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Porters room T511 Under pipe	Cement packer under pipe Small Amounts	Sampled	Cement	Low	Unsealed Cement	Chrysotile	Very Low	4	5	9
1077922/0820	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Store T506	Cream floor tile and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0821	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Waiting room T504	Bitumen membrane 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0822	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Entrance lobby T503	Bitumen membrane 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0823	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T512	Cream floor tile with brown fleck and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0824	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Kitchen T501	Cream floor tile with brown fleck and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0825	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Kitchen T501 Underside of sink	Acoustic pad 1 Item	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0826	Condition Monitoring Survey	Int	St Tydfils Main Building/G	General office T502	Bitumen membrane 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0827	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Porters rest room T506	Acoustic pad 1 Item	Sampled	Bitumen	Low	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0828	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Porters rest room T506	Cream floor tile with brown fleck and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0829	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Porters rest room T506 Fixed ceiling panel	Cement board 10.0m ²	Sampled	Cement	No Visible	Painted/Sealed Cement	Chrysotile	Very Low	2	4	6
1077922/0830	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Visitors wc T507 Fixed ceiling panel	Cement board 10.0m ²	Visually Similar To	Cement	No Visible	Painted/Sealed Cement	Chrysotile	Very Low	2	4	6
1077922/0831	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Stair T508	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0832	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Trolley bay T545	Red linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0833	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Trolley wash T526	Grey linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0834	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Cooking area T547	Ceiling tiles 50.0m ²	Sampled	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0835	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Cooking area T547/cooking prep T548	Above fixed tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0836	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Store T527	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0837	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Catering manager T528	Cream floor tile with brown fleck and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0838	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Trolley bay T545	Black board 10.0m ²	Sampled	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0839	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Cooking prep	Black board 2.00m ²	Visually Similar To	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0840	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Wash area T529	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0841	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Chill prep T549	Black board 2.00m ²	Visually Similar To	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0842	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Pastry and diet prep T550	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0843	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Cooking prep T454 Underside of movable trolley	Acoustic pads 3 items	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	5	8
1077922/0844	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T552	Black board 2.00m ²	Visually Similar To	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0845	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Deep freeze T533	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0846	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Chill room T531	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0847	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Meat and fish prep T532	Cream floor tile with brown fleck and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0848	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Dry store T534	Cream floor tile with brown fleck and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0849	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T553	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0850	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Day store T535	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0851	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Hardware and cookery store T538	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0852	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Veg prep T539	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0853	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Day to day store T548	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0854	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T554	Tiles 50.0m ²	Sampled	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0855	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T555	Tiles 50.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0856	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T554/T555	Above fixed tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0857	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Dry waste store	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0858	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Shower/wc T542	Tiles 50.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0859	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Shower/wc T542	Grey linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0860	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Store T545	Cream floor tile with brown fleck and bitumen 3.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0861	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Hotel services manager T543	Tiles 25.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0862	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Hotel services manager T543	Above fixed tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0863	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Secretary T543a	Tiles 25.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0864	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Secretary T543a	Above fixed tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0865	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Stairs T536	Beige tiles and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0866	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Function Room	Beige tiles and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0867	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Switch room T544	Cream floor tile with brown fleck and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0868	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Switch room T544 Wall	Electric boards N/A	Presumed Asbestos	Rope	No Visible	N/A	Asbestos	Low	5	4	9

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0869	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Store T510	Cream floor tile with brown fleck and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0870	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Abernant room T401	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0871	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Lobby T435	Pale blue linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0872	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Lobby T435	Pale blue linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0873	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T436	Pale blue linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0874	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T436	Pale blue linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0875	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Staff wc T404	Cream tile and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0876	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Staff wc T404	Beige tile and bitumen Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0877	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Clean utility T405 Underside of sink	Acoustic pads 2 Items	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0878	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Equipment store T407	Cream tile and bitumen 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0879	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Bedinog bay T409	Beige tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0880	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Dirty utility T408 Underside of sink	Acoustic pads 2 Items	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/0881	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T437	Cream tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0882	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T437	Brown tile Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0883	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T437	Mustard tile Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0884	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Hirwaun bay T410	Brown tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0885	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Hirwaun bay T410	Deep brown tile and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0886	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Hirwaun bay T410	Mustard colour tiles Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0887	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Laundry T412	Cream tile and bitumen 5.00m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0888	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Laundry T412	Mustard tile Small Amounts	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0889	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Double room T434	Brown tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0890	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Newton bay T426	Brown tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0891	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Cwmdare room T433	Brown tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0892	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Wc T432	Grey linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0893	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Pennar bay T427	Brown tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0894	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Assistant bath and wc T429	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0895	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Assistant wc T430	Grey linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0896	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T442	Cream tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0897	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T442	Mustard tile Small Amounts	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0898	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T442	Brown tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0899	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Assistant bath and wc T411	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0900	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T438	Cream tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0901	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T439	Cream tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0902	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Doctor T414	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0903	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Sister T415	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0904	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Ward pantry T425	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0905	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Sensory room T413	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0906	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Disposal store T426	Grey tile and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0907	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Staircase T416	Brown tiles and bitumen 50.0m ²	Sampled	Vinyl	Low	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0908	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Staircase T416	Peach coloured tile and bitumen Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0909	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Lobby T440	Brown tiles and bitumen 10.0m ²	Visually Similar To	Vinyl	Low	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0910	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Lobby T440	Tan coloured tile and bitumen Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0911	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Store T423	Ceiling tiles 10.0m ²	Sampled	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0912	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Store T423	Cream tile and bitumen 10.0m ²	Sampled	Vinyl	Low	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0913	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Store T423 Wall	Electrical boxes N/A	Presumed Asbestos	Rope	No Visible	N/A	Asbestos	Low	5	4	9
1077922/0914	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Quiet room T417	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0915	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Quit smoking room T422	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0916	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Dining/day room T418	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0917	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Assistant wc T419	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0918	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Assistant wc T420	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0919	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T523	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0920	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T523	Ceiling tiles 50.0m ²	Visually Similar To	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0921	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T523	Paneling 50.0m ²	Sampled	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0922	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T523	Black nosings 2 Items	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0923	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Domestic T424	Grey linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0924	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T523	Above fixed tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0925	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T556	Cream tile and bitumen 10.0m ²	Visually Similar To	Vinyl	Low	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0926	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T556	Ceiling tiles 10.0m ²	Visually Similar To	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0927	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T556	Above fixed ceiling tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0928	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T557	Cream tile and bitumen 50.0m ²	Visually Similar To	Vinyl	Low	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0929	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T557	Ceiling tiles 50.0m ²	Visually Similar To	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0930	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T557	Above fixed tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0931	Condition Monitoring Survey	Int	St Tydfils Main Building/G	X-ray room T515	Cream tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0932	Condition Monitoring Survey	Int	St Tydfils Main Building/G	X-ray room T515	Above fixed tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0933	Condition Monitoring Survey	Int	St Tydfils Main Building/G	X-ray room T514	Cream tile and bitumen 25.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0934	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Office T516	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0935	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Wc T517	Cream tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0936	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Wc T518	Multi coloured linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0937	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Cloaks T520	Cream tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0938	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Changing T519	Cream tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0939	Condition Monitoring Survey	Int	St Tydfils Main Building/G	X-ray room T515 Wall	Electrics N/A	Presumed Asbestos	Rope	No Visible	N/A	Asbestos	Low	5	5	10

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0940	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T522	Cream floor tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0941	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T522	Ceiling tiles 50.0m ²	Visually Similar To	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0942	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T522	Above fixed tiles N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0943	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Waiting T521	Cream floor tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0944	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T522	Infill paneling 10.0m Run	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0945	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Plant room T513	Cream floor tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0946	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Domestic T629	Grey linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0947	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T522	Black nosings Small Amounts	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0948	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Secretary T525	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0949	Condition Monitoring Survey	Int	St Tydfils Main Building/G	League of friends T524	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0950	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Clean utility T614 Underside of sink	Acoustic pads 3 Items	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	Chrysotile	Very Low	2	4	6
1077922/0951	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Clean utility T614	Red tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0952	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Equipment store T612	Cream tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0953	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Nurse station T611	Beige tile 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0954	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Nurse station T611	Cream tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0955	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Staff wc T613	Cream tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0956	Condition Monitoring Survey	Int	St Tydfils Main Building/G	6 bed ward T603	Grey tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0957	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Store T602	Cream tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0958	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Lobby T602	Cream tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0959	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Disabled wc T601	Grey linoleum 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0960	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T633	Cream tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0961	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Single bed ward T604	Grey tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0962	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Single bed ward T605	Grey tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0963	Condition Monitoring Survey	Int	St Tydfils Main Building/G	5 bed ward T610	Grey tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0964	Condition Monitoring Survey	Int	St Tydfils Main Building/G	5 bed ward T609	Grey tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0965	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Assistant bath and wc T608	Grey linoleum 25.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0966	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Assistant wc T607	Grey linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0967	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Wc T606	Grey linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0968	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T634	Cream tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0969	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T634	Green tile 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0970	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Dirty utility T616	Acoustic pad 1 Item	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0971	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Wheel chair store T615	Cream tile and bitumen 25.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0972	Condition Monitoring Survey	Int	St Tydfils Main Building/G	4 bed ward T617	Grey tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0973	Condition Monitoring Survey	Int	St Tydfils Main Building/G	4 bed ward T617	Beige tile and bitumen Small Amounts	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0974	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Disposal T632	Grey floor tile and bitumen 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0975	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Laundry T618	Cream floor tile and bitumen 10.0m ²	Sampled	Vinyl	Low	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0976	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Assisted bath and wc T619	Grey linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0977	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Assistant bath and wc T620	Grey linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0978	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Disposal T621	Grey floor tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0979	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Sister T622	Grey floor tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0980	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T635	Cream floor tile and bitumen 10.0m ²	Visually Similar To	Vinyl	Low	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0981	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T636	Cream floor tile and bitumen 10.0m ²	Visually Similar To	Vinyl	Low	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0982	Condition Monitoring Survey	Int	St Tydfils Main Building/G	ECG store T637a	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0983	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Store T630	Cream floor tile and bitumen 10.0m ²	Visually Similar To	Vinyl	Low	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0984	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Store T630	Tiles 10.0m ²	Sampled	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/0985	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Store T630 Wall	Electrics N/A	Presumed Asbestos	Rope	No Visible	N/A	Asbestos	Low	5	4	9
1077922/0986	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Lobby T637 Floor	Brown tile and bitumen 10.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	Chrysotile	Very Low	2	5	7
1077922/0987	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Stairs over ECG store	Brown nosings 50.0m Run	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0988	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Stairs over ECG store Floor	Brown tile and bitumen 10.0m ²	Visually Similar To	Bitumen	No Visible	Reinforced - Composite Materials	Chrysotile	Very Low	2	3	5
1077922/0989	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Stairs over ECG store	Cream floor tile and bitumen Small Amounts	Visually Similar To	Vinyl	Low	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0990	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Dining/day room T628	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/0991	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Assistant wc T625	Grey linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0992	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Assistant wc T624	Grey linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0993	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Quiet room T623	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0994	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Quiet room T627	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0995	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Chiropodist T628	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0996	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Lobby T636a	Cream floor tile and bitumen 10.0m ²	Visually Similar To	Vinyl	Low	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/0997	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Ward pantry T707 Underside of sink	Acoustic pads 2 Items	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	Chrysotile	Very Low	2	4	6
1077922/0998	Condition Monitoring Survey	Int	St Tydfils Main Building/G	OT activities room T706	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/0999	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T714	Cream tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1000	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Store T704	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1001	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Office T705	Cream tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1002	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T724	Black nosing 1 Item	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1003	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T702	Beige linoleum 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1004	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Wc T772	Beige linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1005	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Waiting room T703	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1006	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Female wc T709	Cream tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1007	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Male wc T706	Cream tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1008	Condition Monitoring Survey	Int	St Tydfils Main Building/G	ECT treatment T723	Acoustic pad 1 Item	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/1009	Condition Monitoring Survey	Int	St Tydfils Main Building/G	ECT treatment T723	Beige linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1010	Condition Monitoring Survey	Int	St Tydfils Main Building/G	ECG recovery T701	Beige linoleum 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1011	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Store T721	Cream tile and bitumen 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1012	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Corridor T710	Cream tile and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1013	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Dirty utility T720 Underside of sink	Acoustic pads 2 Items	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	Chrysotile	Very Low	2	4	6
1077922/1014	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Dirty utility T720 Wall	Electrics N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1015	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Dirty utility T720	Grey linoleum 25.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1016	Condition Monitoring Survey	Int	St Tydfils Main Building/G	ADL kitchen T719	Acoustic pad 1 Item	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1017	Condition Monitoring Survey	Int	St Tydfils Main Building/G	ADL kitchen T719	Maroon flecked tile 10.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1018	Condition Monitoring Survey	Int	St Tydfils Main Building/G	ADL kitchen T718	Brown coloured tile and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1019	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Day/dining/activit y room T711	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1020	Condition Monitoring Survey	Int	St Tydfils Main Building/G	ADL bathroom T718	Grey linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1021	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Medical records T717	Cream tiles and bitumen 50.0m ²	Sampled	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1022	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Office T716	Cream tiles and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1023	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Community Psychological nurse T712	Cream tiles and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1024	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Assistant wc T713	Grey linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1025	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Assistant wc T715	Grey linoleum 10.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1026	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Day room T714	Cream tiles and bitumen 50.0m ²	Visually Similar To	Vinyl	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/1027	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Pipe tunnel	No Access N/A	Presumed Asbestos	Thermal Lagging	No Visible	N/A	Asbestos	Low	6	0	6
1077922/1028	Condition Monitoring Survey	Ext	St Tydfils Main Building/G	Yard 1	Felt roof 50.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1029	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Plant room T537 Ceiling	Insulating panels 10.0m ²	Sampled	Insulating Board	No Visible	Painted/Encapsulated Board	Amosite	Low	5	4	9
1077922/1030	Condition Monitoring Survey	Ext	St Tydfils Main Building/G	Yard 2 Wall	Bitumen membrane 50.0m Run	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	1	4
1077922/1031	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Over hotel services managers office and secretary office	No Asbestos N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1032	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Over kitchen stores etc. Flat roof	Bitumen felt 50.0m ²	Presumed Asbestos	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	2	5
1077922/1033	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Beneath disposal T426	Room containing pipe work N/A	Presumed Asbestos	Thermal Lagging	No Visible	N/A	Asbestos	Low	6	0	6
1077922/1034	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Store room T455	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1035	Condition Monitoring Survey	Ext	St Tydfils Main Building/G	Corridor T523/T557 Wall above and below windows	Red painted panels 50.0m ²	Sampled	Cement	No Visible	Painted/Sealed Cement	Chrysotile	Very Low	2	6	8
1077922/1036	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Loading bay	Underside of hangover 50.0m ²	Sampled	Cement	No Visible	Painted/Sealed Cement	No Asbestos Detected	Non asbestos	0	0	0
1077922/1037	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Loading bay	Tongue and groove 50.0m ²	Sampled	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/1038	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Loading bay	Roof felt 10.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1039	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Loading bay	Bitumen Small Amounts	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1040	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Loading bay	Insulation board 10.0m ²	Sampled	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/1041	Condition Monitoring Survey	Int	St Tydfils Main Building/G	All areas Floor	Ducts N/A	Presumed Asbestos	Thermal Lagging	No Visible	N/A	Asbestos	Low	6	0	6

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/1042	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/G	Builders store	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1043	Condition Monitoring Survey	Ext	St Tydfils, Workshops/F 1	Builders store Flat roof	Felt 25.0m ²	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	Chrysotile	Very Low	2	2	4
1077922/1044	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Electricians store FF38 Shelves	Fuse flash guards Small Amounts	Sampled	Rope	No Visible	N/A	Asbestos Removed	Non asbestos	0	0	0
1077922/1045	Condition Monitoring Survey	Int	St Tydfils, Workshops/F 1	Plumber FF39	Insulating tile Small Amounts	Sampled	Insulating Board	Medium	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/1046	Condition Monitoring Survey	Ext	St Tydfils, Workshops/G	Plumber FF38/store FF34 Roof edges and centre	Ridge sections 10.0m ²	Sampled	Cement	Low	Unsealed Cement	Chrysotile	Very Low	4	1	5
1077922/1047	Condition Monitoring Survey	Ext	St Tydfils Main Building/G	Plumber FF38/store FF34 Roof	Profiled sheets 50.0m ²	Sampled	Cement	Low	Unsealed Cement	Chrysotile	Very Low	4	2	6
1077922/1048	Condition Monitoring Survey	Int	St Tydfils Main Building/G	Toilets FF28	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1049	Condition Monitoring Survey	Ext	St Tydfils Main Building/F 1	Toilets FF28	Bitumen membrane 50.0m Run	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0
1077922/1050	Condition Monitoring Survey	Ext	St Tydfils Main Building/F 1	Roof of stores Roof	Replacment tiles Small Amounts	Sampled	Cement	Low	Unsealed Cement	Chrysotile	Very Low	4	1	5
1077922/1051	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Roof of new part over front entrance of day care unit and on second floor roof Roof	Tiles Small Amounts	Presumed Asbestos	Cement	Low	Unsealed Cement	Chrysotile	Very Low	4	2	6
1077922/1052	Condition Monitoring Survey	Int	St Tydfils Main Building/B	Workshop 1 032	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1053	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 16 031	No Suspect ACMs N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1054	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Lobby 030	No Suspect ACM Observed N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1055	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Entrance lobby GF05	Tongue and groove panels 10.0m ²	Sampled	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/1056	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/G	Underside of ambulance drop off canopy	Tongue and groove panels 50.0m ²	Visually Similar To	Insulating Board	No Visible	Painted/Encapsulated Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/1057	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Duct 029 Wall on cables	Debris Small Amounts	Sampled	Debris	High	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/1058	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Duct 029 Top of pipes	Debris Small Amounts	Sampled	Debris	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/1059	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Duct 029 Wall	Debris Small Amounts	Sampled	Debris	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/1060	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Duct 029 Floor	Debris Small Amounts	Sampled	Debris	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/1061	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Duct 029 Floor/wall	Debris Small Amounts	Sampled	Debris	Visible Debris	Debris	Asbestos Removed	Non asbestos	0	0	0
1077922/1062	Condition Monitoring Survey	Int	St Tydfils Day Care unit/B	Workshop 3, 034	General Observations N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1063	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Workshop 2, 033	General Observations N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1064	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 18, 036	General Observations N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1065	Condition Monitoring Survey	Int	St Tydfils Day Care Unit/B	Store 17, 035	General Observations N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1066	Condition Monitoring Survey	Ext	St Tydfils, Central Offices/F 2	Roof	No access tank room to roof N/A	Presumed Asbestos	Insulating Board	No Visible	N/A	Asbestos	Low	5	0	5
1077922/1067	Condition Monitoring Survey	Int	St Tydfils, Workshops/G	Incinerator 01/Store 02	Board 20.0m ²	Sampled	Insulating Board	No Visible	Unsealed Board	No Asbestos Detected	Non asbestos	0	0	0
1077922/1068	Condition Monitoring Survey	Ext	St Tydfils Incinerator House/G	Incinerator/Store 01 Roof	Tiles 40.0m ²	Sampled	Cement	No Visible	Unsealed Cement	Chrysotile	Very Low	3	2	5
1077922/1069	Condition Monitoring Survey	Ext	St Tydfils Incinerator House/G	Incinerator/Store 01 Wall	Bitumen membrane 40.0m Run	Sampled	Bitumen	Low	Reinforced - Composite Materials	Chrysotile	Very Low	3	1	4
1077922/1070	Condition Monitoring Survey	Ext	St Tydfils, Workshops/G	Salt stores	Bitumen membrane 50.0m Run	Sampled	Bitumen	No Visible	Reinforced - Composite Materials	No Asbestos Detected	Non asbestos	0	0	0

St Tydfils Hospital - showing 1083 records														
Assess' Number	Survey Type	Int / Ext	Building/Floor	Location and Position	Description and Extent	Material Identification	Product Type	Damage / Deterioration	Surface Treatment	Asbestos Type	Material Risk Category	Material Risk	Priority Risk	Total Risk
1077922/1071	Condition Monitoring Survey	Ext	St Tydfils, Workshops/G	Salt stores Wall	Redundant flue pipe 1.00m Run	Sampled	Cement	Low	Unsealed Cement	Chrysotile	Very Low	4	1	5
1077922/1072	Condition Monitoring Survey	Int	St Tydfils, Workshops/G	Generator House 01 Generator exhaust	Flange gasket 1 Item	Sampled	Gasket	No Visible	Reinforced - Composite Materials	Chrysotile	Very Low	3	4	7
1077922/1073	Condition Monitoring Survey	Int	St Tydfils, Workshops/G	Generator House 01	Rope 50.0m Run	Sampled	Rope	No Visible	Encapsulated Textile/Paper	No Asbestos Detected	Non asbestos	0	0	0
1077922/1074	Condition Monitoring Survey	Int	St Tydfils, Workshops/G	Generator House 01 Wall	Live switch gear Small Amounts	Presumed Asbestos	Rope	No Visible	N/A	Asbestos	Low	5	3	8
1077922/1075	Condition Monitoring Survey	Int	St Tydfils, Workshops/G	Generator House 01	Floor duct N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1076	Condition Monitoring Survey	Ext	St Tydfils Day Care Unit/G	Store GF44 Below window	White panel 10.0m ²	Sampled	Cement	No Visible	Painted/Sealed Cement	Chrysotile	Very Low	2	2	4
1077922/1077	Condition Monitoring Survey	Ext	St Tydfils, Workshops/G	Chimney Stack Lining	Panel N/A	Presumed Asbestos	Insulating Board	No Visible	N/A	Asbestos	Low	5	0	5
1077922/1078	Condition Monitoring Survey	Ext	St Tydfils, Workshops/G	Tanks Lining	No access N/A	Presumed Asbestos	Insulating Board	No Visible	N/A	Asbestos	Low	5	0	5
1077922/1079	Condition Monitoring Survey	Ext	St Tydfils Day Care unit/G	Front entrance Facia	Fascia board/soffit 30.0m Run	Sampled	Cement	Low	Painted/Sealed Cement	Chrysotile	Very Low	3	2	5
1077922/1080	Condition Monitoring Survey	Ext	St Tydfils Main Building/F 1	Lift motor room Wall	Cement sheets 10.0m ²	Sampled	Cement	Low	Painted/Sealed Cement	Chrysotile	Very Low	3	2	5
1077922/1081	Condition Monitoring Survey	Int	St Tydfils Main Building/F 1	Lift Motor Rooms Lift machinery	Brake Pad 2 Items	Presumed Asbestos	Cement	Low	Unsealed Cement	Asbestos	Low	6	5	11
1077922/1082	Condition Monitoring Survey	Int	St Tydfils, Workshops/G	Water Tank	General Observations N/A	No Suspect ACM	Select Product	No Visible	N/A	No Asbestos Detected	Non asbestos	0	0	0
1077922/1083	Condition Monitoring Survey	Int	St Tydfils, Psychiatric Unit/F 3	Psychiatric Unit Lift Plant room electrical box	Rope Small Amounts	Presumed Asbestos	Rope	No Visible	N/A	Asbestos	Low	5	4	9
1077922/1084	Condition Monitoring Survey	Int	St Tydfils Main Building/F 3	Main block lift plant room Electrical Box	Electrical Board Small Amounts	Presumed Asbestos	Rope	No Visible	N/A	Asbestos	Low	5	2	7